

Smoothing & Post-Processing Tips

SOURCE:

<https://support.zortrax.com/apoller-tips-tricks/>

Table Of Contents

Smoothing Effect
Smoothing Process
Post-Processing
Other Tips

Smoothing Effect

	ACETONE	MEK
Z-ABS	Glossy finish, layers on vertical surfaces are invisible	Glossy finish, layers on vertical surfaces are invisible
Z-ASA Pro	Semi-matte finish, layers on vertical surfaces are invisible	Semi-matte finish, layers on vertical surfaces are invisible
Z-ULTRAT	Glossy finish, layers on vertical surfaces are invisible	Glossy finish, layers on vertical surfaces are invisible
Z-ULTRAT Plus	Semi-matte finish, layers on vertical surfaces are invisible	Semi-matte finish, layers on vertical surfaces are invisible
Z-HIPS	No reaction	Glossy finish, layers on vertical surfaces are invisible

The Zortrax Apoller removes visible layers from items 3D printed with **Z-ABS**, **Z-ULTRAT**, **Z-ULTRAT Plus**, **Z-ASA Pro**, and **Z-HIPS**, or their third-party equivalents. However, materials produced by other companies may bring slightly different effects during the smoothing process. The table specifies the final effects of the surface finish on models printed with Zortrax materials.

If you want to obtain a stronger smoothing effect, use the *HIGH* option while selecting the smoothing intensity in the menu. Also, butanone (MEK) provides slightly more intense effects than acetone.

It is not recommended to use the same models during multiple smoothing processes to increase their smoothing effect. It will surely have a negative influence on their surface quality.

Smoothing Process



Models intended for smoothing can be placed on the glass platform in the device or can be suspended on the hooks in the grid installed in the chamber. You can use both methods during one smoothing process, but remember to keep proper spaces between models (3-5 cm [1.2-2 in]). If you put too many models inside the chamber or you don't keep spaces between them, the vapors circulation will be interrupted and the smoothing effect will be uneven. It is also important to place models 5 cm [2 in] away from the chamber walls.

If there are some parts of your model that you want to protect from being smoothed, cover them with kapton tape. The tape has good resistance against solvents and is able to withstand high temperatures that occur during the smoothing process.

Post-Processing



Removing residues

Support structures, material residues or any surface imperfections should be removed from the 3D printed object with a scalpel, knife or pliers before smoothing in the Zortrax Apoller. It is not recommended to remove residues or defects with sandpaper because marks which remain after sanding will be clearly visible on the model's surface after the smoothing process.

Still, if you decide on sanding your model, use sandpaper with as fine grit as possible. Once you finish sanding, wipe the object with a wet cloth to remove dust.

Gluing parts

Models which consist of several parts should be glued before the smoothing process, preferably with the same substance that will be used for smoothing. Thanks to that, the risk of damaging the bond between parts during the smoothing process will be reduced, and the connection will be less visible afterwards.

Prepare a colorless brush. Use the brush to cover the parts which you want to glue together with acetone or butanone (MEK). Connect both parts and wait until they bond.

The model glued in such a way is ready to be smoothed in the Zortrax Apoller.



Painting smoothed parts

Before painting, the already smoothed part should be covered with a coat of primer to ensure better adhesion of the paint. You can also roughen the part's surface by sandblasting it with very fine particles.

Moveable mechanisms

Moveable mechanisms, including gears, bearings or hinges, usually retain their capacity to move after the smoothing process. However, mechanisms in which there is a large contact area between individual elements may not move after smoothing. In that case, separate the glued surfaces by slightly "cracking" the mechanism.

Other Tips



Launching the next smoothing process

If you want to launch one smoothing process after another, make sure to cool the platform to room temperature. The smoothing may not be conducted properly when the platform has not cooled down.

Micro-cracking on Z-HIPS models

Models printed with Z-HIPS can sometimes have micro-cracks on their surface after the smoothing process. If you notice small white lines on your part, use a heat gun to remove them. Set the device to $\sim 100^{\circ}\text{C}$ [212°F].